




PRODUCT DATASHEET

Product Name	NuPower II	
Manufacturer	Nuvite	
Part Number	N006 – 5 US Gallon N216 – 1 US Gallon	
Available Pack Sizes	1 & 5 US Gallon	
Qualifications	Douglas CSD #1, Boeing D6-17487, AMS 1650 AIMS 09-00-002	

DESCRIPTION

Nuvite's **NuPower II** is an extraordinary product for ongoing care of painted or polished metal surfaces. It is easily applied with a wipe-on, wipe-off procedure with pad applicators or by hand in all types of humidity conditions. NuPower II is a hi-tech formulation that offers cleaning power, a bright shine, and a protective barrier coating against surface oxidation that also protects against ultraviolet deterioration. Because NuPower II is so easy and fast to use, it offers significant savings in labour and retains maximum appearance protection and performance in both fleet and heavy service situations.

FEATURES

- Exceptional soil dispersion power
- Removes surface oxidation from paint and metal surfaces.
- Easy wipe on, let dry, wipe off to a clean, bright surface.
- Safe to all aircraft components.
- Adds a beautiful gloss appearance with an effective ultraviolet protectant coating on both painted and metal surfaces.
- Easy application in all climates.
- Preserves and protects substrate from further oxidation and leaves a protective coating against u/v and atmospheric corrosion/salt spray/ pollution without colour change.
- Offers superior cleaning results and protection with fewer man-hours and a low material requirement.

DIRECTIONS FOR USE

For Normal or Lightly Soiled Surface Conditions:

Apply NuPower II "as is" by hand with a soft wiping cloth, applicator pad/mop or working quickly and lightly with slow speed orbital buffer to small areas at a time. Agitate area evenly with wet material. Allow to fully dry (usually no more than 5-10 minutes even in the highest humidity conditions). Remove by wiping off with clean mop head or dry wiping cloth to reveal shine.

Frasers Aerospace

1 St James Road, Brentwood, Essex, CM14 4LH, United Kingdom.

Tel: +44 (0) 20 8597 8781 Fax: +44 (0)20 8597 8673

Web: www.frasersaerospace.com Email: contact@frasersaerospace.com

For Heavily Soiled Surface Conditions:

For the heavy grease, oil, and hydraulic oil build-ups, it is sometimes helpful that the area be wiped down or degreased with Nuvite CitriCut or CitriCut Gel degreasing cleaners prior to the use of NuPower II, then proceed as above. For heavy dirt or carbon and fluid surface stain areas, use Nuvite NuPol to remove.

HEALTH & SAFETY CONSIDERATIONS

NuPower II is not environmentally restricted. Users should use standard safety precautions, such as wearing gloves and eye protection along with any other standard safety procedures. Refer to Material Safety Data Sheet for further information.

Frasers Aerospace

1 St James Road, Brentwood, Essex, CM14 4LH, United Kingdom.

Tel: +44 (0) 20 8597 8781 Fax: +44 (0)20 8597 8673

Web: www.frasersaerospace.com Email: contact@frasersaerospace.com